

FIG. 1




FIG. 2




FIG. 3




FIG. 4




Figure 5




FIG. 6

PT2800_2002 File Zoom Tools Help 11:57

CSA-Zone / Location

Work Order No.: JKA1234-01

Service Type: 500

Model: 320BL
S/N: 3CR01256
RPM Industries, Inc.

Zone: 1

Loc: WASHINGTON

Other: This is the notes field for assigned WOs

Back Continue

Main Data

Figure 7




FIG. 8




FIG. 9

802

802B

802C

802D

802A

Pocket_PC

File Zoom Tools Help

CSA-Zone/Location 11:00

Work Order No.: RPM505816-01

Service Type: 250

Model: 777D
S/N: AGC01999
RPM Industries, Inc.

Zone: 1

Loc: CORAOPOLIS

Other: <Other>

Back Continue

Main Data

FIG. 10

902

: PockeTPC Phone

File Zoom Tools Help

CSA-Service Type

Work Order No.: 26-01

Model: 1434

S/N: 1100

Vulcan Materials

Electrical

Service Type: 0000098765

Last Service Type: 2000

Last Serviced: 1500

11/11/02

Back S.O.S. Label Continue

New Options Print

902A

902B

902C

902D

902E

902F

902G

902H

902I

FIG. 11





FIG. 12

Serial No	Compartment ID	Oil Added	Sample Date	Meter Reading	Hours On Oil	Application	Fluid ID	Viscosity ID	Oil Changed
ABCD5678	Engine	12	6/19/03 9:44 PM	250	250	Light	Engine Oil	15W40	True
ABCD5678	Transmission	0	6/19/03 9:44 PM	250	250	Medium	Transmission Oil	30	False
ABCD5678	Hydraulic	0	6/19/03 9:44 PM	250	250	Medium	Hydraulic Oil	10	False
ABCD5678	Left Rear Final	0	6/19/03 9:44 PM	250	250	Heavy	Final Drive Oil	50	False
ABCD5678	Right Rear Final	0	6/19/03 9:44 PM	250	250	Heavy	Final Drive Oil	50	False
ABCD5678	Rear Differential	0	6/19/03 9:44 PM	250	250	Heavy	Final Drive Oil	50	False
ABCD5678	Engine	12	6/26/03 7:53 AM	525	275	Light	Engine Oil	15W40	True
ABCD5678	Transmission	10	6/26/03 7:53 AM	525	525	Medium	Transmission Oil	30	True
ABCD5678	Hydraulic	0	6/26/03 7:53 AM	525	525	Medium	Hydraulic Oil	10	False
ABCD5678	Left Rear Final	0	6/26/03 7:53 AM	525	525	Heavy	Final Drive Oil	50	False
ABCD5678	Right Rear Final	0	6/26/03 7:53 AM	525	525	Heavy	Final Drive Oil	50	False
ABCD5678	Rear Differential	0	6/26/03 7:53 AM	525	525	Heavy	Final Drive Oil	50	False
ABCD5678	Engine	12	7/3/03 8:24 AM	800	275	Light	Engine Oil	15W40	True
ABCD5678	Transmission	0	7/3/03 8:24 AM	800	275	Medium	Transmission Oil	30	False
ABCD5678	Hydraulic	0	7/3/03 8:24 AM	800	800	Medium	Hydraulic Oil	10	False
ABCD5678	Left Rear Final	0	7/3/03 8:24 AM	800	800	Heavy	Final Drive Oil	50	True
ABCD5678	Right Rear Final	0	7/3/03 8:24 AM	800	800	Heavy	Final Drive Oil	50	True
ABCD5678	Rear Differential	0	7/3/03 8:24 AM	800	800	Heavy	Final Drive Oil	50	False
ABCD5678	Engine	12	7/14/03 3:14 PM	1000	200	Light	Engine Oil	15W40	True
ABCD5678	Transmission	0	7/14/03 3:14 PM	1000	475	Medium	Transmission Oil	30	False
ABCD5678	Hydraulic	0	7/14/03 3:14 PM	1000	1000	Medium	Hydraulic Oil	10	False
ABCD5678	Left Rear Final	0	7/14/03 3:14 PM	1000	200	Heavy	Final Drive Oil	50	False
ABCD5678	Right Rear Final	0	7/14/03 3:14 PM	1000	200	Heavy	Final Drive Oil	50	False
ABCD5678	Rear Differential	0	7/14/03 3:14 PM	1000	1000	Heavy	Final Drive Oil	50	True

Figure 13






FIG. 15





FIG. 16

Pocket_PC

File Zoom Tools Help

Single Phase Load Ban

11:51

Time: 11:50

AB TEMP

HZ:

VOLTS:

AMPS:

KW CAL:

OIL

OIL

PRES

TEMP

EXH TEMP

RB:

LB:

WATER

TEMP:

IN:

WATER

FUEL

OUT:

PRES:

EXTRA:

EXTRA:

EXTRA:

EXTRA:

Cancel

OK

1302

FIG. 17

Pocket_PC

File

Zoom

Tools

Help

3 Phase Load Bank Test

3:07

Time:

15:07

AMB TEMP

HZ:

VOLTS:

AMPS: 1

2

3

AVG:

KW CAL:

OIL

OIL

PRES

TEMP

EXH TEMP

RB:

LB:

WATER

WATER

TEMP:

IN:

WATER

FUEL PRES:

OUT:

EXTRA:

OK

Cancel

1402

FIG. 18

1602

1602A

1602B

1602C

1602D

1602E

Pocket_PC
 File Zoom Tools Help
 CSA Service Report 7:15
 Dealer Code: 44 Date: 5/7/03
 Work Order: W2242 Segment: 01
 Customer Name: RPM Industries, Inc. | 1
 Model/SN: Dump 1234567
 Equipment Location: Stone mountain
 Co Equip #: 2 At SN:
 Employee ID: 1 Hrs: 1502
 Miles:
 Instructions:
 Cancel Continue

FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30

:PPT2800_2002
 File Zoom Tools Help
 CSA-SN 8:56

Customer: RPM Industries, Inc.
 Serial No.: 7FR04069
 Make: CAT Model: B36
 Year: 2000
 Hrs: 1235
 Descr: Earth Moving Compact
 Zone: 00
 Location: Washington
 Service Interval: 250

Cancel Add
 Main Data

Figure 31

:PPT2800_2002
 File Zoom Tools Help
 CSA-SN 8:57

Confirmation
 Tap OK to add 7FR04069
 Make: CAT
 Model: B36
 Year: 2000
 Location: Washington
 Service Interval: 250
 Customer: RPM Industries, Inc. To the equipment table

OK Cancel
 Cancel Add
 Main Data

Figure 32

: PPT2800_2002
 File Zoom Tools Help
 Power Systems 9:01 OK

*Engine SN: 4BK00679
 Unit Site No: 07854
 Site Address: 55 Hickory Street
 Washington, PA 15301
 Contact:
 Phone:
 Customer: RPM Industries, Inc. | 1

Back Continue

Fig. 33

: PPT2800_2002
 File Zoom Tools Help
 Power Systems 9:05 OK

Gen Make: CAT
 Gen Model: 54162
 Gen SN: 3BS00645
 Voltage: 220 Amps: 90
 KW: 1250
 Gen Spec:

Back Continue

Fig. 34

: PPT2800_2002
 File Zoom Tools Help
 Power Systems 10:16 K

Air Filter Make: FRAM
 Air Filter PN: 123-4567
 Air Filter QTY: 2
 Oil Filter Make: FRAM
 Oil Filter PN: 987-6543
 Oil Filter QTY: 4

Back Continue

Fig. 35

: PPT2800_2002

File Zoom Tools Help

Power Systems 10:18

Primary

Fuel Filter Make:

Fuel Filter PN:

Fuel Filter Qty:

Secondary

Fuel Filter Make:

Fuel Filter PN:

Fuel Filter Qty:

Back Continue

Fig. 36

: PPT2800_2002

File Zoom Tools Help

Power Systems 10:18

Belt

Belt Make:

Belt PN:

Belt Qty:

Oil / Coolant

Oil Type:

Oil Qty:

Coolant Qty:

Back Continue

Fig. 37

: PPT2800_2002

File Zoom Tools Help

Power Systems 10:19

Battery Charger

Bat Chrg Make:

Bat Chrg Model:

Bat Chrg SN:

Input Volts:

Output Volts:

Output Amps:

Back Continue

Fig. 38

File Zoom Tools Help

Power Systems

Battery Charging

Alternator Make:

Alternator Model:

Alternator SN:

Output Amps:

Batteries

Group No:

CCA:

NiCad:

QTY:

Lead Acid:

Other:

Back

Continue

Fig. 39

File Zoom Tools Help

Power Systems

Block Heater Make:

Block Heater Model:

Block Heater SN:

Block Heater Watts:

Block Heater Voltage:

Back

Continue

Fig. 40

File Zoom Tools Help

Power Systems

Starter Make:

Starter Model:

Starter SN:

Starter Rotation:

Starter QTY:

Back

Continue

Fig. 41

PPT2800_2002 File Zoom Tools Help

Power Systems 10:21 OK

Transfer Switch Make:

Transfer Switch Model:

Transfer Switch SN:

Transfer Switch Volts:

Transfer Switch Amps:

Transfer Switch Options:

Back Continue

Fig. 42

PPT2800_2002 File Zoom Tools Help

Power Systems 10:22 OK

Other:

Other Make:

Other PN:

Other QTY:

Power System Equipment Note:

Clear Back Finish

Fig. 43

PPT2800_2002 File Zoom Tools Help

CSA-SN 11:51

RPM CSA

Te Created Record OK

Powersystems Equipment Saved.

Earth Moving ☐ Power Systems ☒

S/N: 4665

New

Back Continue

Main Data

Fig. 44

Question 8: Sample screen displays specific to performing an unassigned work order function with the PDA.

The screenshot shows a PDA screen with a title bar containing ': PPT2800_2002', 'File', 'Zoom', 'Tools', 'Help', and window control icons. Below the title bar is a menu bar with 'CSA-SN' and a back arrow icon. The main area features the RPM CSA logo, followed by technician and customer details. At the bottom, there are radio buttons for 'Earth Moving' (selected) and 'Power Systems', a 'New' button, and a 'Continue' button. A 'Main Data' tab is visible at the very bottom.

Technician: John Apostolidas
Date: 08/14/03
Time: 14:08
Customer: RPM Industries, Inc. | 1
☒ Earth Moving ☐ Power Systems
S/N: AGC00734
New
Continue

Fig. 45

The screenshot shows a PDA screen with a title bar containing ': PPT2800_2002', 'File', 'Zoom', 'Tools', 'Help', and window control icons. Below the title bar is a menu bar with 'CSA-Work Order' and a back arrow icon. The main area features the RPM CSA logo, followed by work order details. At the bottom, there are 'Back' and 'Continue' buttons. A 'Main Data' tab is visible at the very bottom.

Work Order:
Segment: 01
Customer No.: 1
Equipment No.: N/A
Hours Meter: 0000002375
Service Type: 250
Last Service Type: 500
Last Serviced: 06/19/03
Back
WO Notes
Continue

Fig. 46




Fig. 47




Fig. 48

: PPT2800_2002 File Zoom Tools Help

CSA Service Report 2:13

Dealer Code: H16C Date: 08/14/03

Work Order: B14218 Segment: 01

Customer Name: RPM Industries, Inc. | 1

Caterpillar Model/SN: 777D AGC0199

Equipment Location: CORAOPOLIS

Co Equip #: 4 At SN:

Employee ID: 0 Hrs: 625 Miles:

Instructions:
Customer reports trouble with the steering pump and tank. This is a possible warranty situation.

Cancel Continue

Fig. 49

: PPT2800_2002 File Zoom Tools Help

CSA Service Report 2:17 OK

Part Number Responsible: 123-4567

Part Name: Gear QTY: 2

Desc code: D-Factory Assembly

Group Number Containing Part: B6-4811

Group Name: Pump

Did this incident make the product inoperable: No

Optional Comments: No Lid Gasket

Back Add Continue

Fig. 50

: PPT2800_2002 File Zoom Tools Help

CSA Service Report 2:21

Incidents:

Part Num...	Part Name	QTY
123-4567	Gear	2
987-6543	Cover	1
456-9123	Gasket	1

Back Add Continue

Fig. 51

:PPT2800_2002
 File Zoom Tools Help
 CSA Service Report 2:22

PARTS

Left With Customer:

Scrapped:

Return No:

Job Complete:

Back Continue

Fig. 52

:PPT2800_2002
 File Zoom Tools Help
 CSA Service Report 2:24

WHAT DID YOU FIND WRONG:

The gasket between the pump and the pump cover was missing causing the gear to gouge the lid and leak.

Back Continue

Fig. 53

:PPT2800_2002
 File Zoom Tools Help
 CSA Service Report 2:26

WHAT WAS DONE TO REPAIR THE PROBLEM:

Due to extensive damage I had to replace the pump.

Back Continue

Fig. 54




Fig. 55




Fig. 56




Fig. 57




Fig. 58




Fig. 59






FIG. 60



4002

FIG. 61



4102

FIG. 62




FIG. 63





FIG. 64

4302






FIG. 66




Fig. 67




Fig. 68




Fig. 69




Fig. 70




Fig. 71




Fig. 72





Fig. 73



4702

FIG. 74




FIG. 75

4802

Product Family Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Stop Search Favorites Home

Address http://www.rpiindustries.org/templates/ProductFamily.aspx

Product Family Administration

Administration Customer Create CSA Inspection

User Admin Product ID: 32

Check List Admin *Product Description

Division Admin Submit

Location Admin

Role Admin

Fluid Admin

Template Admin

SOS Compartment Admin

Service Report Admin

Product ID	Description
	Underground Articulated Truck
	Articulated Dump Truck
	Asphalt Paver
	Barhee Loader
	Challenger
	Cold Planer
	Combe
	Earth Moving Compactor
	Engineer Support Tractor
	Excavator
	Forest Products
	Generator
	Integrated Tool Carrier
	Load Haul Dump
	Mini Hydraulic Excavator
	Motor Grader
	Off Highway Truck/Tractor
	Paving Compactor
	Pipe Layer
	Road Reclaimer/Soil Stabilizer
	Skid Steer Loader

FIG. 76

4902




FIG. 77

5002




FIG. 79

5202

Contract Administration - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address http://www.rpmindustries.org/empiretest/ContractDetail.aspx?AgreementNo=123456&id=1

Go Links

Contract Administration

Administration Customer Create CSA Inspection View Contracts

Customer Number 2

Agreement Number 123456

Engine SN
6HND0251
81201234
FDND0485

Note: To select more than one Engine SN
keep Ctrl button pressed and click Engine SN

Contact

Phone

Fax

Fager

FCSF

Service Area

Start Date

Length 1234

P.O. none

Expires 12/1/2005

Per Year Interval 0

Level 1 Charges 0

Level 2 Charges 0

Level 3 Charges 0

Done Internet

FIG. 80

5302



FIG. 81

Equipment Detail - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Search Favorites Media

Address: <http://www.rpmindustries.org/emp/ebot/EquipmentDetail.asp?SerialNo=3CR01256>

Equipment Detail

Administration Customer Create CSA Inspection Equipment Admin

Equipment Number	3
*Serial Number	3CR01256
Make	CAT
Model	320BL
Year	1999
Description	Underground Articulated Truck
Customer Number	1
Customer Name	RPM Industries, Inc.
Location	WASHINGTON
Equipment Zone	1
Last Service Type	250
Last Service Date	9/14/2001 5:56:00 PM
Meter Reading	257
Service Interval	250

Submit

FIG. 82

5502




FIG. 84

5702




FIG. 85

5802

2 Inspection Type Notes - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media Print

Address http://www.rpmindustries.org/templates/notes_html.asp?customer=RPIN201inc.%20Inc.&type=1&work=TOMD418032&equi=SN1234567

Go Links

Inspection Type Notes

Customer Name: RPM Industries, Inc. Customer No: 1

Mechanical: 0 Model: Dump Serial No: 0

Type of Service: 500 Meter Hours: Electrical: 1502

Equipment No: SN1234567 Date: 9/15/2001 6:32:00 AM

Work Order Number: TOMD418032

Cooling System
Cooling system note.

Done

Internet

5902

FIG. 86

Work Order Notes - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Search Favorites Media

Address http://www.ipmindustries.org/empiretest/checknote_print.asp?custname=Motorola%20Inc%2012&type=fbw&id=MZ111&eqid=FDND0485

Inspection Checklist Item Notes

Customer Name: Motorola Mos 12
Mechanical: 0
Type of Service: 2
Equipment No: FDND0485

Customer No: 2
Serial No: 0
Meter Hours: Electrical: 000000000
Date: 4/23/2003 4:59:00 PM
Work Order Number: MZ111

Inspect cooling system hoses

minimal wear but customer demands replacement.

Done

6002

FIG. 87

Service Reports - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back

Forward

Stop

Search

Home

Print

Stop

Reload

Go

Links

Address http://www.rpmindustries.org/emp/etst/ServiceReport_print.asp?authname=RPM%20Industries,%20Inc.&empno=AGC00734%20%20&mod=502334

Service Reports

Attachment Serial No:

Serial No: 1

Location: 00

Hours: 507

Miles: 7770

Model: 7770

Instructions:

Equipment No:

Work Order Number:

Dealer Code: T14

Work Order Date: 4/17/2003 12:00:00 AM

Employee ID: 15

Customer: RPM Industries, Inc.

Part No	Part Responsible Name	QTY	Description	Group No	Containing Part	Did this incident make the product inoperable?	Comments
9y8400	reg	1	B	1406	none	True	By

Previous

Next

WHAT DID YOU FIND WRONG?

Found Wills

WHAT WAS DONE TO REPAIR THE PROBLEM?

PARTS

Left with Scrapped Return	Job
Customer	Complete
Yes	No
No	Yes

Done

6102

FIG. 88

Repairs Report - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Search Favorites Media

Address: http://www.rpautilities.org/engr/etes/RepairsReport_cptk.asp?WO=7777

Units

Required Repair Reports

Work Order Number:

Model: 35168

Serial No:

Equipment No: 0

Last Serviced:

Work Order Date & Time: 4/23/2003 3:44:00 PM

Segment: 01

Last Service Type: 0

Current Service Type: 1

Employee:

Customer: Motorola Mos 12

Electrical Meter: 0000000000

Mechanical Meter: 0

Zone Location: N/A

Location:

CheckList Item	CheckList Response
In Phase Monitor	RR
Inspect radiator/heat exchanger	RR
Inspect cooling system hoses	RR

Done

Internet

6202

FIG. 89

CSA Inspection - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back

Forward

Stop

Home

Search

Print

Media

Links

Address

http://www.rpmindustries.org/emptest/WorkOrder_Phr.asp?WO=MZ1111&custno=2

Work Order Number: MZ1111

Date: 4/23/2003 4:59:00 PM

Mechanical: 0

Customer Name: Motorola Mos 12

Customer No: 2

Equipment No: 35168

Serial No: 0

Type of Service: 2

Meter Hours: Electrical: 0000000000

CSA Inspection Report

Cooling System		
Inspect radiator/heat exchanger	RR	Check cooling leaks
Check filler cap	OK	Record freeze/boil over protection
Inspect cooling system hoses	RR	Inspect hose clamps
Check fan drive/pulleys	OK	Check water pump
Check block heater	OK	Check Radiator Hoses
Lubrication, Fuel & Air Systems		
Replace oil & lube filters	OK	Collect oil sample
Inspect engine for oil leaks	OK	Inspect crankcase breather
Replace fuel filters	OK	Drain water from separators
Inspect fuel priming pump	OK	Inspect fuel filters
Inspect fuel tank	OK	Inspect day tank/controls
Check all fuel lines	OK	Replace air filters
Inspect air filter housing	OK	Inspect air filter seals/clamps/pathways
Inspect all louvers/passageways	OK	
Cranking & Charging Systems		
Check Alternator output voltage	OK	Check battery electrolyte level
Check battery specific gravity	OK	Check battery charger output voltage
Check battery charger output amperage	OK	Check all battery cables

Done Internet

FIG. 90

Create CSA Inspection - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Address: http://www.rpmindustries.org/cresta/test/CreatesWO.aspx

Create CSA Inspection

Time to be completed: 4:00 AM PM

Time to be completed: May 2003

Sun	Mon	Tue	Wed	Thu	Fri	Sat
1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

Create

Assign CSA Inspection

Administration Customer Assigned CSA Inspections

*Work Order Num: MD59876

Segment: D1

*Customer: RPM Industries, Inc.

*Earth Moving *Power Systems

Serial Num: AGC01999

Technician: John Apostolides

Template: earth

Load Template

Questions: Select an Question to Add

WOID	InspectionTypeID	SortOrder	Description	ResponseID	ServiceIntervalID
MD59876	1	10	Balls at Equalizer Bar End Caps	3	250
MD59876	2	43	Spindle (Left)	3	250
MD59876	1	12	Track Adjustment	3	250
MD59876	1	21	Hydraulic Oil Changed?	1	250
MD59876	2	41	Pivot Shaft	3	250
MD59876	2	44	Spindle (Right)	3	250
MD59876	2	46	Steering	3	250
MD59876	2	49	Tandems (Right)	3	250

FIG. 91

6402

Assigned CSA Inspections - Microsoft Internet Explorer
File Edit View Favorites Tools Help
Back Forward Stop Search Favorites Media
Address http://www.rpmindustries.org/empiretest/assignedWO.aspx
Assigned CSA Inspections
Assigned CSA Inspections
Administration Customer Create CSA Inspection

Work Order ID	Customer	Technician (First Name)	Technician (Last Name)	Serial Number	Segment	Power Systems	Date	Time
Delete	RPM Industries, Inc	John		AGC0199901		False	5/28/2003	4:00 PM
Delete	RPM Industries, Inc	John		AGC0073401		False	5/14/2003	7:00 AM
Delete	RPM Industries, Inc	Thomas		AGC0199901		False	5/13/2003	7:00 AM
Delete	best company	Thomas		12345	02	True	4/23/2003	11:11 PM
Delete	best company	Thomas		321	01	False	4/21/2003	11:11 PM
Delete	RPM Industries, Inc	Thomas		AGC0199901		False	4/29/2003	7:00 AM
Delete	RPM Industries, Inc	Will		AGC0199901		False	5/5/2003	8:00 AM
Delete	Motorola Mds 12	Will		6HN0025101		True	4/30/2003	8:30 AM
Delete	Motorola Mds 12	Will		EDM0048505		True	4/28/2003	8:30 AM

6502

FIG. 92